

To: All customers and all distributors

Production-Discontinuation: RCA and RCS2 Arm Type

December 2021

Dear Sir and Madam,

Thank you for being our valued customer. We appreciate your continued business and support.

Due to difficulty of continuing to produce the following models, we would like to announce herewith a production discontinuation.

- | | |
|-------------------------------|--|
| 1. Affected models | : The following models |
| | • RCA-A4R/A5R/A6R |
| | • RCS2-A4R/A5R/A6R |
| 2. Reason for discontinuation | : Due to the low volume of recent orders |
| 3. Successor models | : Please find the next page. |
| 4. Order cutoff date | : January 26, 2022 |
| 5. Repair service cutoff date | : January 26, 2032 |
| | * We may have to stop servicing them once the corresponding spare parts are no longer available. |

We sincerely apologize for any inconvenience caused by the discontinuation of the products and ask for your understanding and cooperation.

Best regards,

IAI Industrieroboter GmbH
Ober der Röth 4
65824 Schwalbach am Taunus
Tel.: +49-6196-8895-0, Fax: +49-6196-8895-24
E-Mail: info@iai-automation.com, Web: iai-automation.com

Successor models of RCA and RCS2 Arm Type

The successor models are the similar models in RCP6 and RCS4 Table type. Please check the details in the catalogues, because the dimension and specification are different.

Discontinued models	Successor models	Note
RCA-A4R	RCP6/RCS4-TA4R	Dimension and specification are different
RCS2-A4R		
RCA-A5R	RCP6/RCS4-TA6R	
RCS2-A5R		
RCA-A6R		
RCS2-A6R		