

To: All customers and all distributors

Production discontinuation: RCP2 with 56P motor

February 2024

Dear Sir and Madam,

Thank you for being our valued customer. We appreciate your continued business and support.

Due to difficulty of continuing to produce the following models, we would like to announce herewith a production discontinuation.

- | | |
|-------------------------------|---|
| 1. Affected models | : All RCP2 models equipped with 56P motor
Please see next page for details. |
| 2. Reason for discontinuation | : Production discontinuation of components of relevant motors |
| 3. Successor models | : RCP6 series
* Product dimension and installation dimension are different.
Please see the latest product catalog for details.
Also mechanically compatible RCP4 models can be offered
as special solution. Please contact IAI for details. |
| 4. Order cutoff date | : 26. June 2024 |
| 5. Repair service cutoff date | : 26. June 2034
* We may have to stop service earlier, if the relevant parts
are no longer available. |

We sincerely apologize for any inconvenience caused by the discontinuation of the products and ask for your understanding and cooperation.

Best regards,

IAI Industrieroboter GmbH
Ober der Röth 4
65824 Schwalbach am Taunus
Tel.: +49-6196-8895-0, Fax: +49-6196-8895-24
E-Mail: info@iai-automation.com Web: iai-automation.com

List of all RCP2 models equipped with 56P motor

Series	Type	Replacement model
RCP2	RA6C	RCP6-RA7C
	RGD6C	RCP6-RRA7C
	RGS6C	RCP6-RRA7C
	RMA	RCP6-RA7C
	RMGD	RCP6-RRA7C
	RMGS	RCP6-RRA7C
	SA7	RCP6-SA7C
	SA7C	RCP6-SA7C
	SA7R	RCP6-SA7R
	SM	RCP6-HSA7C
	SMR	RCP6-SA8R
	SS8C	RCP6-HSA7C
	SS8R	RCP6-SA8R
RCP2CR	SA7	RCP6CR-SA7C
	SA7C	RCP6CR-SA7C
	SM	RCP6CR-SA8C
	SS8C	RCP6CR-SA8C
RCP2	RMW	RCP6W-RA7C
RCP2W	RA6C	RCP6W-RA7C