

To: All customers and all distributors

Production discontinuation: RCA2-RN*N/RP*N/GS*N/GD*N/SD*N

August 2023

Dear Sir and Madam,

Thank you for being our valued customer. We appreciate your continued business and support.

Due to difficulty of continuing to produce the following models, we would like to announce herewith a production discontinuation.

- | | |
|-------------------------------|---|
| 1. Affected models | : RCA2-RN3N/RP3N/GS3N/GD3N/SD3N,
RCA2-RN4N/RP4N/GS4N/GD4N/SD4N |
| 2. Reason for discontinuation | : Due to availability of the successor models |
| 3. Successor models | : RCA2-* NA (e.g. RCA2-RN3 NA)
* Please find the further detail in the next page. |
| 4. Order cutoff date | : 23. September 2023 |
| 5. Repair service cutoff date | : 23. September 2023
* We may have to stop service sooner if the relevant parts are no longer available. |

We sincerely apologize for any inconvenience caused by the discontinuation of the products and ask for your understanding and cooperation.

Best regards,

IAI Industrieroboter GmbH
Ober der Röth 4
65824 Schwalbach am Taunus
Tel.: +49-6196-8895-0, Fax: +49-6196-8895-24
E-Mail: info@iai-automation.com Web: iai-automation.com

Replacement models for RCA2-RN*N/ RP*N/ GS*N/ GD*N/ SD*N

Discontinued model	Replacement model	Notes
RCA2-RN3N	RCA2-RN3N <u>A</u>	Product dimension and installation dimension are compatible.
RCA2-RP3N	RCA2-RP3N <u>A</u>	
RCA2-GS3N	RCA2-GS3N <u>A</u>	
RCA2-GD3N	RCA2-GD3N <u>A</u>	
RCA2-SD3N	RCA2-SD3N <u>A</u>	
RCA2-RN4N	RCA2-RN4N <u>A</u>	
RCA2-RP4N	RCA2-RP4N <u>A</u>	
RCA2-GS4N	RCA2-GS4N <u>A</u>	
RCA2-GD4N	RCA2-GD4N <u>A</u>	
RCA2-SD4N	RCA2-SD4N <u>A</u>	

Note for controller

If only the actuator is replaced, the following change is required.

1. RCA2-*3N : Update of the controller firmware and change of parameters
 - a. ACON-SE/CY/PO/PL, RACON : from v001B
 - b. ACON-C/CG (PIO- type) : from v001D
 - c. ACON-C/CG (Field network type) : from v000B
 - d. ASEP/AMEC : from v000A

2. RCA2-*4N : Change in the parameters

Please contact IAI or your distributor to make these changes with expert assistance.