



To: All customers and all distributors

Production-Discontinuation: RCS series

April 2019

Dear Sir and Madam,

Thank you for being our valued customer. We appreciate your continued business and support.

Due to difficulty of continuing to produce the following models, we would like to announce herewith a production discontinuation.

- | | |
|-------------------------------|---------------------------------|
| 1. Affected models | : All RCS series |
| 2. Reason for discontinuation | : Recommending successor models |
| 3. Successor models | : Please find the next page |
| 4. Order cutoff date | : September 30, 2019 |
| 5. Repair service cutoff date | : September 30, 2029 |
- * We may have to stop servicing them once we are out of the parts in stock that are no longer manufactured prior to the end of the service period.

We sincerely apologize for any inconvenience caused by the discontinuation of the products and ask for your understanding and cooperation.

Best regards,

IAI Industrieroboter GmbH
Ober der Röth 4
65824 Schwalbach am Taunus
Tel.: +49-6196-8895-0, Fax: +49-6196-8895-24
E-Mail: info@iai-gmbh.de, Web: www.iai-gmbh.de

Replacement models for RCS series

Slider type

Discontinued model	Replacement model	Notes
RCS-SA4	RCA-SA4D	Successor models with installation compatibility
RCS-SA5	RCA-SA5D	
RCS-SA6	RCA-SA6D	
RCS-S4	RCA-SS4D	
RCS-S5	RCA-SS5D	
RCS-S6	RCA-SS6D	
RCS-SS	RCS2-SS7C	Successor models Motor unit coupled
RCS-SM	RCS2-SS8C	
RCS-SSR	RCS2-SS7R	Successor models with full compatibility (only change in article)
RCS-SMR	RCS2-SS8R	

Rod type

Discontinued model	Replacement model	Notes
RCS-RA35-GN	RCA-RA3C	Successor models without installation compatibility
RCS-RA35-GS	RCA-RGS3C	
RCS-RA35-GD	RCA-RGD3C	
RCS-RA45-GN	RCA-RA4C	
RCS-RA45-GS	RCA-RGS4C	
RCS-RA45-GD	RCA-RGD4C	
RCS-RA55-GN	RCA-RA5C	
RCS-RA55-GS	RCA-RGS5C	
RCS-RA55-GD	RCA-RGD5C	
RCS-RA35R	RCA-RA3R	
RCS-RA45R	RCA-RA4R	
RCS-RA55R	RCA-RA5R	
RCS-RB7525-GN	RCS2-SRA7BD	
RCS-RB7525-GS	RCS2-SRGS7BD	
RCS-RB7525-GD	RCS2-SRGD7BD	
RCS-RB7530-GN	RCS2-SRA7BD	
RCS-RB7530-GS	RCS2-SRGS7BD	
RCS-RB7530-GD	RCS2-SRGD7BD	
RCS-RB7535-GN	RCS2-SRA7BD	Successor models with installation compatibility by option
RCS-RB7535-GS	RCS2-SRGS7BD	
RCS-RB7535-GD	RCS2-SRGD7BD	

Flat type

Discontinued model	Replacement model	Notes
RCS-F45	Please choose the available table types	
RCS-F55	RCS2-F5D	Successor models with full compatibility (only change in article)

Gripper type

Discontinued model	Replacement model	Notes
RCS-G20	RCS2-GR8	Successor models with full compatibility (only change in article)

Rotary type

Discontinued model	Replacement model	Notes
RCS-R10	RCS2-RT6	Successor models with full compatibility (only change in article)
RCS-R20	RCS2-RT6R	
RCS-R30	RCS2-RT6	Successor models without installation compatibility