

To: All customers and all distributors

Production-Discontinuation: ROBONET-Controller

May 2022

Dear Sir and Madam,

Thank you for being our valued customer. We appreciate your continued business and support.

Due to difficulty of continuing to produce the following models, we would like to announce herewith a production discontinuation.

- | | |
|-------------------------------|---|
| 1. Affected model | : ROBONET-Controller (RGW/RPCON/RACON/RABU/REXT) |
| 2. Reason for discontinuation | : The discontinuation of its supplier |
| 3. Successor models | : Please find the next page. |
| 4. Order cutoff date | : 23 June 2022 |
| 5. Repair service cutoff date | : 23 June 2032
* We may have to stop service sooner if the relevant parts are no longer available. |

We sincerely apologize for any inconvenience caused by the discontinuation of the products and ask for your understanding and cooperation.

Best regards,

IAI Industrieroboter GmbH
Ober der Röth 4
65824 Schwalbach am Taunus
Tel.: +49-6196-8895-0, Fax: +49-6196-8895-24
E-Mail: info@iai-automation.com Web: iai-automation.com

Replacement models for ROBONET-Controller

RCON is available as the successor model. Please check the details in the catalogs because the product dimensions, specifications and operation modes are different.

Discontinued model	Replacement model	Notes
RGW	RCON-GW	Product dimensions, specifications and modes of operation are different. - Solenoid valve modes 1 and 2 are not available at RCON. - With RCON, the maximum number of positions in positioning mode 1 and 2 is 128 points. (ROBONET: max. 768 points) - Motor and encoder cables must be replaced. - Parameters and Position data are not compatible
RPCON	RCON-PC	
RACON	RCON-AC	
RABU	RCON-ABU	
REXT	-	